

Exclusion List for HWL NavDBs in Cycle 2404

Listed below are all terminal procedures that are removed from the ARINC 424 file provided to Honeywell for AIRAC cycle 2404. This list does not compromise procedures or other data that have been removed during processing by the Data Packer (Honeywell).

Type	Procedure	Reason*
06N		Middletown/Randall
	APCH	
	R08	5
	R26	5
012		Brazil Clay County
	APCH	
	R27	5
12N		Andover/Aeroflex/Andover
	APCH	
	R03	5
2W2		Westminster/Clairview Airpark
	APCH	
	R14	5
9A5		Lafayette/Barwick Lafayette
	APCH	
	R02	5
	R20	5
CYYT		St Johns Intl
	APCH	
	R10-X	5
	R16-X	5
EBBE		Beauvechain
	APCH	
	I04LY	5
	I22RX	5
	I22RY	5
	L04LY	5
	L22RX	5
	L22RY	5
	T04LY	5
	T04R	5
	T22L	5
T22RY	5	

*See Reason Code table on page R1

Type	Procedure	Reason*
------	-----------	---------

SID		
	BE04C	5
	BE04D	5
	BE04W	5
	BE22A	22
	BE22B	22
	BE22C	5
	BE22D	5
	BE22W	5

EBBL

Kleine Brogel

APCH

	T05R	5
	T23L	5

SID

	BL05A	22
	BL05B	22
	BL05D	22

EBFS

Florennes

SID

	FS08A	22
	FS08B	22
	FS08C	22
	FS26A	22
	FS26B	22
	FS26C	22

EGHC

Penzance/Land s End

APCH

	H07	5
	H16	5
	H25	5
	H34	5

EGHE

St Mary's/Scilly Isles

APCH

	N27	5
	N32	5

EGJA

St Annes/Alderney

APCH

	N08	5
	N26	5

*See Reason Code table on page R1

	Type	Procedure	Reason*
EGNH			Blackpool
	APCH	N10	3
EGNV			Teesside International
	APCH	N23	3
EGPO			Stornoway
	APCH	L36	3
		N18	3
		N36	3
EGTE			Exeter
	APCH	N26	3
EHEH			Eindhoven
	SID	EH5	22
ENBL			Forde/Bringeland
	APCH	J07	1
		J25	1
ENBN			Bronnoysund/Bronnoy
	APCH	J03	1
ENBS			Batsfjord
	APCH	J03	1
		J21	1
ENBV			Berlevag
	APCH	J06	1
		J24	1
ENHF			Hammerfest
	APCH	J04	1
		J22	1

*See Reason Code table on page R1

	Type	Procedure	Reason*
ENHK			Hasvik
		APCH	
		J11	1
		J29	1
ENLK			Leknes
		APCH	
		J20	1
ENMH			Mehamn
		APCH	
		J17	1
		J35	1
ENNM			Namsos
		APCH	
		J07	1
		J25	1
ENRM			Rorvik/Ryum
		APCH	
		J04	1
		J22	1
ENRS			Rost
		APCH	
		J02	1
		J20	1
ENSH			Svolvaer/Helle
		APCH	
		J36	1
ENSS			Vardo/Svartnes
		APCH	
		J15	1
		J33	1
ENST			Stokka/Sandnessjoen
		APCH	
		J02	1
		J20	1
ENVD			Vadso
		APCH	
		J07	1
		J25	1

*See Reason Code table on page R1

	Type	Procedure	Reason*
EPPR			Pruszcz Gdanski
		APCH	
		N27-X	5
		N27-Y	5
		N27-Z	5
ETEB			Ansbach-Katterbach Kaserne
		APCH	
		H08	5
		H26	5
ETIK			Illesheim
		APCH	
		R06	5
		R24	5
ETNG			Geilenkirchen
		SID	
		NG227	22
EVLA			Liepaja
		APCH	
		I24-Z	5
		V06-Z	5
		V24-Z	5
		SID	
		LEP1E	5
		LEP1G	5
KDLH			Duluth Intl
		APCH	
		T09	19
		T09-Y	19
		T09-Z	19
KDYS			Abilene/Dyess AFB
		APCH	
		T16-W	19
		T16-X	19
		T34-W	19
		T34-X	19

*See Reason Code table on page R1

	Type	Procedure	Reason*
KEGI			Crestview/Duke Fld, Eglin AF A
		APCH	
		T18-Y	19
		T18-Z	19
		T36-Z	19
KENV			Wendover
		APCH	
		R08	5
KLSV			Las Vegas/Nellis AFB
		APCH	
		T03R	19
		T21LX	19
		T21LY	19
		T21LZ	19
KMFR			Medford/Rogue Valley Intl-Medf
		APCH	
		R32-Y	5
KMTC			Mount Clemens/Selfridge ANGB
		APCH	
		T01	19
		T19	19
KMTN			Baltimore/Martin State
		APCH	
		T15	19
		V15	11
KNDZ			Milton/Whiting Fld NAS South
		APCH	
		T32	19
KPAM			Panama City/Tyndall AFB
		APCH	
		T14LY	19
		T14LZ	19
		T14RY	19
		T32LY	19
		T32RY	19
		T32RZ	19
KVKX			Friendly/Potomac Airfield
		APCH	
		R06	5

*See Reason Code table on page R1

Type	Procedure	Reason*
KVPS		Valparaiso/Destin-Ft Walton Be
	APCH	
	T02-Z	19
	T12-Z	19
	T20-Z	19
	T30-Z	19
LFBD		Bordeaux/Merignac
	SID	
	ROYA5Z	5
	SAU5Z	5
	VAVI5Z	5
LHKE		Kecskemet
	APCH	
	N12	5
	N30	5
LHNY		Nyiregyhaza
	APCH	
	H18-Z	5
	H36-Z	5
LHPA		Papa AB
	APCH	
	N16	5
LJCE		Cerklje ob Krki
	APCH	
	N09	22
MHTG		Tegucigalpa/Toncontin Intl
	APCH	
	H20	13
MMAN		Monterrey/Del Norte Intl
	APCH	
	D20-4	2
MSSS		San Salvador/Ilopango Intl
	APCH	
	V15-W	5
N07		Lincoln Park
	APCH	
	R01	5
	R19	5

*See Reason Code table on page R1

	Type	Procedure	Reason*
N40			Pittstown/Sky Manor
		APCH	
		R07	5
		R25	5
		V07	5
N85			Pittstown/Alexandria
		APCH	
		D08	5
NTAA			Tahiti/Faa'a
		SID	
		ARIT4E	5
		ARIT4W	5
NTTE			Tetiaroa
		SID	
		TAVI1E	5
		TAVI1W	5
NZTK			Takaka
		APCH	
		R18-Y	5
NZWB			Woodbourne
		STAR	
		NORTHV	27
		WESTV	27
OPLA			Lahore/Allama Iqbal Intl
		APCH	
		V18LZ	3
		V18RZ	3
		V36L	3
		V36R	3
OPRK			Rahim Yar Khan/Sheikh Zayed In
		APCH	
		V01	3
PACJ			Crooked Creek
		APCH	
		R14	5
	SID		
		AJOFY1	5

*See Reason Code table on page R1

	Type	Procedure	Reason*
PARS			Russian Mission
	APCH	R36	5
RJAH			Hyakuri
	APCH	I03RY	19
		L03RY	19
		T21LY	19
RKSM			Seoul Domestic
	APCH	I20-Z	22
		L19-Z	22
		L20-Z	22
UHHM			Chegdomyn
	APCH	H13	5
		H31	5
UHPK			Ust-Kamchatsk
	STAR	DOMUD2	5
UIUU			Ulan-Ude/Mukhino
	APCH	I08-Y	5
		N08-Y	5
		N08-Z	5
	STAR	BULE5H	5
		OSTU5H	5
		RIDL5H	5
		TOLG5H	5
UKHK			Kremenchuk/Velyka Kokhnyvka
	APCH	N36	5
UNSS			Strezhevoy
	SID	BUNA1Z	22

*See Reason Code table on page R1

Type	Procedure	Reason*
URML		Makhachkala/Uytash
	SID	
	H1A	5
	TA1A	5
	STAR	
	BUIK1E	5
	BUIK1G	5
	GUDE1E	5
GUDE1G	5	
URRT		Taganrog/Yuzhny
	APCH	
	N10-X	5
	N28-X	5
UUYI		Inta
	SID	
	BABE1A	5
	BABE1B	5
	INTA1A	5
	INTA1B	5
	PERA1A	5
	PERA1B	5
	ROLE1A	5
ROLE1B	5	
UWKD		Kazan
	APCH	
	V11-X	5
UWSK		Krasny Kut
	SID	
	X003	5
	X070	5
	X107	5
	X130	5
	X156	5
X351	5	
VTBK		Nakhon Pathom/Kamphaeng Saen
	APCH	
	V21	2

*See Reason Code table on page R1

	Type	Procedure	Reason*
WAJI			Sarmi/Mararena
		APCH	
		H13	5
		H31	5
WAKE			Mappi/Bade
		APCH	
		H02	5
		H20	5
WASA			Maybrat/Ayawasi
		APCH	
		H09	5
		H27	5
WASI			Inanwatan
		APCH	
		H08	5
		H26	5
WAUM			Merdey
		APCH	
		H27	5

*See Reason Code table on page R1

Reason Table HWL

Code	Explanation
1	procedure based on SCAT GBAS system, not accepted by Data Packer
2	VOR and VOR/DME APP published without multiple indicator, VOR-only APP excluded
3	two approaches of same type: only one requires DME. Non-DME-based approach excl.
5	procedure authorized for CAT A aircraft only
11	procedure contains AF (Arc-to-Fix) Path Termination, based on invalid Navaid
13	RNAV (RNP) and RNAV (GNSS) APP published without multiple indicator, RNP APP excluded
19	procedure requires military TACAN receiver
22	procedure contains CR (Course-to-Radial) Path Termination, based on invalid type of Navaid
27	STAR that does not have a common start fix

If you have any questions concerning this report, please contact your FMS Customer Support at fms.support@lhsystems.com or call +41 44 828 65 55